


Key No.	Part Description	Qty.	EIOOELT
	Power Cord Assembly	1	PW117-281-
	Bracket	1	TSIJ
2	Intellishield Switch Ass'y	1	PSI 9-102
3	Impellert	1	PS17-1560
4		1	PS5-35P

NOTE: If motor fails, replace entire pump. t See



Page 8 for impeller replacement instructions.